



Earhart

EQUIPMENT CORPORATION

SALES • RENTAL • PARTS • SERVICE

4350 SOUTH PALO VERDE BLVD
TUCSON, AZ 85714

Phone: 520-889-6396 • Fax: 520-294-7767

Toll Free: 888-EARHART

www.earhartequipment.com

Ship to:

SAME AS BELOW

Invoice to:

EARHART EQUIPMENT CORP
4350 S. PALO VERDE BLVD
TUCSON AZ 85714

Branch		
TUCSON		
Date	Time	Page
04/13/16	14:58:30 (O)	01
Account No.	Phone No.	Invoice No.
EARHA001	520 8896396	W07936
Ship Via	Purchase Order	
10040859-C	860223496	
		Salesperson
		KSD

SERVICE INVOICE

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
24694	POWERSTAR TRACTOR	4	ZFAH03712	
T4.75				

THANK YOU FOR CHOOSING EARHART EQUIPMENT CORPORATION!!!

***** UNIT DESCRIPTION *****
* TRACTORS POWERSTAR TRACTOR *

REPAIR# 1 C 486 N/A 03/31/16 04/01/16 04/01/16

REPAIR LEAK ON TOP OF TRANSMISSION

COMPLAINT:

FOUND THAT THERE IS A LEAK ON TOP OF THE TRANSMISSION

CAUSE:

Trans valve leaking from mating surface right side mid section

took pics and submitted a assist/ with pics ordered trans control valve. Please see assist U0650446

CORRECTION:

installed new trans controller valve reinstalled all hard lines and fuel tank. filled trans to operation level. operated test drove 1/4 mile rechecked for leaks none present.

tagged and turned in control valve to warranty dept.

FRT	FREIGHT	1	139.85	139.85
14456981	O-RING	RETAIL	7.00	
		5 N	3.13	15.65
47412408	VALVE, PRE	RETAIL	2002.00	
		1 N	1351.35	1351.35
5135738	O-RING	RETAIL	3.25	
		4	1.30	5.20
84577713	GASKET	RETAIL	25.92	

CONTINUED ON PAGE 02

THIS INVOICE IS NOW DUE AND PAYABLE

All bills are due 10th of month following date of invoice. A finance charge of 1.5% (18% annual percentage rate) will be added to overdue accounts. A minimum charge of \$2.00 on all overdue accounts.
ALL MERCHANDISE RETURNED SUBJECT TO A 15% RE-STOCKING CHARGE. NO REFUND WITHOUT THIS RECEIPT. NO REFUND ON SPECIAL ORDERS OR ELECTRICAL ITEMS. NO REFUNDS AFTER 30 DAYS.
"Seller retains title to the goods sold until the buyer pays for same in full. Seller retains a security interest in the goods. Including all accessions to and replacements of them, to secure performance of buyers obligations of payment. Buyer assumes all risk of loss of said goods upon delivery of same to buyer by seller."

X

LIMITED WARRANTY AND LIMITATION OF LIABILITY - PARTS AND ACCESSORIES. This is a limited warranty. The manufacturer and the selling Dealer jointly warrant each new part and accessory to be free from defects in material and workmanship under normal use and service for a period of 3 months from the date of sale at retail or for the remainder of the original equipment warranty, whichever is greater. The only exception to this warranty is for batteries and tires in which case the Battery/Tire Adjustment Policy will apply.
ALL MERCHANDISE RETURNED SUBJECT TO A 15% RE-STOCKING CHARGE. NO REFUND WITHOUT THIS RECEIPT. NO REFUND ON SPECIAL ORDERS OR ELECTRICAL ITEMS. NO REFUNDS AFTER 30 DAYS.



Earhart

EQUIPMENT CORPORATION

SALES • RENTAL • PARTS • SERVICE

4350 SOUTH PALO VERDE BLVD
TUCSON, AZ 85714

Phone: 520-889-6396 • Fax: 520-294-7767

Toll Free: 888-EARHART

www.earhartequipment.com

Ship to:

SAME AS BELOW

Invoice to:

EARHART EQUIPMENT CORP
4350 S. PALO VERDE BLVD
TUCSON AZ 85714

Branch TUCSON		
Date 04/13/16	Time 14:58:30 (O)	Page 02
Account No. EARHA001	Phone No. 520 8896396	Invoice No. W07936
Ship Via		Purchase Order
10040859-C		860223496
		Salesperson KSD

SERVICE INVOICE

STK#/FLEET# 24694 POWERSTAR TRACTOR HRS 4 PIN/EIN ZFAH03712 WARRANTY DATE HRS
T4.75

10800001 12031001

1 N 14.40 14.40
PARTS 1526.45
LABOR 1159.74
REPAIR TOTAL==> 2686.19

REPAIR# 2 C 486 N/A 03/31/16 04/01/16 04/01/16
DELIVERY AND PICK UP
COMPLAINT:
PICK UP AND DELIVERY

***** WORK ORDER TOTALS *****
INTERNAL CUSTOMER

PARTS 1526.45
LABOR 1159.74
DELIVERY 01
PICKUP 01
INTERNAL TOTAL 2686.21

THIS INVOICE IS NOW DUE AND PAYABLE

All bills are due 10th of month following date of invoice. A finance charge of 1.5% (18% annual percentage rate) will be added to overdue accounts. A minimum charge of \$2.00 on all overdue accounts.
ALL MERCHANDISE RETURNED SUBJECT TO A 15% RE-STOCKING CHARGE. NO REFUND WITHOUT THIS RECEIPT. NO REFUND ON SPECIAL ORDERS OR ELECTRICAL ITEMS. NO REFUNDS AFTER 30 DAYS.
"Seller retains title to the goods sold until the buyer pays for same in full. Seller retains a security interest in the goods. Including all accessories to and replacements of them, to secure performance of buyers obligations of payment. Buyer assumes all risk of loss of said goods upon delivery of same to buyer by seller."

X

LIMITED WARRANTY AND LIMITATION OF LIABILITY - PARTS AND ACCESSORIES. This is a limited warranty. The manufacturer and the selling Dealer jointly warrant each new part and accessory to be free from defects in material and workmanship under normal use and service for a period of 3 months from the date of sale at retail or for the remainder of the original equipment warranty - whichever is greater. The only exception to this warranty is for batteries and tires in which case the Battery/Tire Adjustment Policy will apply.
ALL MERCHANDISE RETURNED SUBJECT TO A 15% RE-STOCKING CHARGE. NO REFUND WITHOUT THIS RECEIPT. NO REFUND ON SPECIAL ORDERS OR ELECTRICAL ITEMS. NO REFUNDS AFTER 30 DAYS.

CO - 01 EARNHART EQUIPMENT
 CR#: W07336 EARNHART EQUIPMENT CORPORA

DIV - 01 EARNHART EQ

BR - 01 TUCSON

Outstanding Only

*****Selection Criteria*****

NM

REQ #	C Item	Quantity	Seg	LOTTTN	Rate/Price	Amount	Description	Cost	Extended Cost	Profit
Q17302	7 PRT	1	01	C	NM	139.85	139.85	0.00	139.85	
R06164	7 LABOR 35020401 A	3.35	01	C	NM	102.00	341.70	24.00	365.70	261.30
R06164	7 LABOR 35020401 A	3.00	01	C	NM	102.00	306.00	24.00	330.00	234.00
R06164	7 LABOR 35020401 A	1.52	01	C	NM	102.00	155.04	24.00	179.04	119.56
R06164	7 LABOR 35020401 A	3.48	01	C	NM	102.00	354.96	24.00	378.96	271.44
R06164	7 LABOR 35020401 A	0.02	01	C	NM	102.00	2.04	24.00	26.04	1.56
Q17302	7 OTHERDEL	1	01	C	NM	127.50	127.50	0.00	127.50	127.50
Q17302	7 OTHERDEL	1	01	C	NM	127.50	127.50	0.00	127.50	127.50
Q17302	7 14455981	5	01	C	NM	3.13	15.65	3.13	18.78	0.00
Q17302	7 47413408	1	01	C	NM	1,351.35	1,351.35	1,351.35	2,702.70	0.00
Q17302	7 5135738	1	01	C	NM	1.30	1.30	1.20	2.50	.10
Q17302	7 5135738	3	01	C	NM	1.30	3.90	1.20	5.10	.30
Q17302	7 84577713	1	01	C	NM	14.40	14.40	14.40	28.80	.00
Total -->		25.37				2,941.19	2,941.19	65.39	3,006.58	1,282.11
Final Total -->						2,841.19		1,659.08	4,490.27	1,282.11

** END OF REPORT **

ASIST

Concern Details

	<u>Incident Number</u>	<u>Logged Date</u>	<u>Closed Date</u>
	U0650446	1-Apr-2016	4-Apr-2016
Dealer	7415 EARHART EQUIPMENT CO - <i>peter mckenna</i>		
Status	Answered	End User	
Subject	OIL LEAK FROM VALVE BLOCK		
Area of Concern	Transmission - 21		
Product Information:			
Base Model	T4.75		
Base Serial No.	ZFAH03712		
Engine Hours	12		
Amount of Use	0	Type of Use	

Concern Description:

Symptom: transmission control vale leaking at transmission body and valve body gasket looks like the transmission shuttle valve is not machined correctly has high spots and machine markings that look low. trans valve bolts were checked for proper torque before removal. all bolts were tight. intermediate metal gasket has no damage. and looks to be evenly compressed when it was installed at factory.

Action: have taken picks to be attached and have got are parts dept involved to see if a valve body is available at this time for replacement. we wanted to inform you first before we ordered a replacement part under warranty. please take a look at pictures and advise.

Question: Please advise.

Resolution:

Dwayne Houck 4 April 2016

SN: ZFAH03712 – T4.75 PowerStar Tier 4 Ankara – ROP – 4WD
(744580) – 12x12 Power shuttle with creeper (334176) – 540 PTO
(743565) – Build: 09/28/2015

1) It is difficult to decipher from photographs however it does appear that irregularities are present in the power shuttle control valve body sealing surface. These irregularities may be causing the leak between the transmission housing and the power shuttle control valve.

2) If the power shuttle control valve body surface irregularities are resulting in leakage replacement of the power shuttle control valve assembly would be recommended.

3) If additional information or assistance is needed please reactivate this concern. Thank you for using ASIST.

Attachments

Attachments