



SANY
AMERICA INC.

SERVICE REPORT

Addendum II

Customer: VALLEY WIDE	Location: TRONA	Work Order: W 017368
Equipment: R.T. CRANE	Model: SRC 865	S/N: 12RC00551253
Hours/Mileage: 474	Delivery date: 9-4-2013	Failure: HAND THROTTLE
Problem Reported: NO HAND THROTTLE		
Problem Found: FOUND LOW VOLTAGE ON THROTTLE COLLECTOR RING		
Repairs performed: CLEAN COLLECTOR RINGS WITH ELEC. CLEANER GOT HAND THROTTLE TO WORK		
Hours worked		
Expenses		
Travel time out: 3.5 hrs	Photos:	
Start: 4:00 Stop: 7:30	Meals:	
Hours on job: 4.5 hrs	Flights:	
On: 7:30 Off: 12:00	Tolls:	
Travel time in: 3.5 hrs	Misc:	
Start: 12:00 Stop: 3:30	Total: \$	
Date: 10-1-2014	Miles Start: 115218	Stop: 115464 Total: 246
Signature Customer:		
Signature SANY: RoB		

